

API No. <u>42-461-43354</u> Drilling Permit # <u>911120</u> SWR Exception <u>(R37)</u>		RAILROAD COMMISSION OF TEXAS OIL & GAS DIVISION APPLICATION FOR PERMIT TO DRILL, RECOMPLETE, OR RE-ENTER <i>This facsimile W-1 was generated electronically from data submitted to the RRC.</i> <i>A certification of the automated data is available in the RRC's Austin office.</i>				FORM W-1 07/2004 Permit Status: Approved	
1. RRC Operator No. 101413		2. Operator's Name (as shown on form P-5, Organization Report) FIREBIRD ENERGY II LLC		3. Operator Address (include street, city, state, zip): 111 BOLAND ST STE 300 FORT WORTH, TX 76107-0000			
4. Lease Name TXL W 3542 H		5. Well No. 304H					
GENERAL INFORMATION							
6. Purpose of filing (mark ALL appropriate boxes): <input checked="" type="checkbox"/> New Drill <input type="checkbox"/> Recompletion <input type="checkbox"/> Reclass <input type="checkbox"/> Field Transfer <input type="checkbox"/> Re-Enter <input type="checkbox"/> Amended <input type="checkbox"/> Amended as Drilled (BHL) (Also File Form W-1D)							
7. Wellbore Profile (mark ALL appropriate boxes): <input type="checkbox"/> Vertical <input checked="" type="checkbox"/> Horizontal (Also File Form W-1H) <input type="checkbox"/> Directional (Also File Form W-1D) <input type="checkbox"/> Sidetrack							
8. Total Depth 8700		9. Do you have the right to develop the minerals under any right-of-way ? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		10. Is this well subject to Statewide Rule 36 (hydrogen sulfide area)? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
SURFACE LOCATION AND ACREAGE INFORMATION							
11. RRC District No. 7C		12. County UPTON		13. Surface Location <input checked="" type="checkbox"/> Land <input type="checkbox"/> Bay/Estuary <input type="checkbox"/> Inland Waterway <input type="checkbox"/> Offshore			
14. This well is to be located <u>23.7</u> miles in a <u>SW</u> direction from <u>MIDKIFF</u> which is the nearest town in the county of the well site.							
15. Section 34	16. Block 42 T5S	17. Survey T&P RR CO / ODESSA RANCH CO		18. Abstract No. A-1481	19. Distance to nearest lease line: ft.	20. Number of contiguous acres in lease, pooled unit, or unitized tract: 995.9	
21. Lease Perpendiculars: <u>500</u> ft from the <u>SOUTH</u> line and <u>1370</u> ft from the <u>WEST</u> line. 22. Survey Perpendiculars: <u>500</u> ft from the <u>SOUTH</u> line and <u>1370</u> ft from the <u>WEST</u> line.							
23. Is this a pooled unit? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		24. Unitization Docket No:		25. Are you applying for Substandard Acreage Field? <input type="checkbox"/> Yes (attach Form W-1A) <input checked="" type="checkbox"/> No			
FIELD INFORMATION List all fields of anticipated completion including Wildcat. List one zone per line.							
26. RRC District No.	27. Field No.	28. Field Name (exactly as shown in RRC records)		29. Well Type	30. Completion Depth	31. Distance to Nearest Well in this Reservoir	
7C	85279200	SPRABERRY (TREND AREA)		Oil or Gas Well	8600	644.00	
BOTTOMHOLE LOCATION INFORMATION is required for DIRECTIONAL, HORIZONTAL, AND AMENDED AS DRILLED PERMIT APPLICATIONS (see W-1H attachment)							
Remarks See W1 Comments attached				Certificate: I certify that information stated in this application is true and complete, to the best of my knowledge. <u>Carter Ann Gordon, Regulatory Analyst</u> <u>Oct 14, 2025</u> Name of filer Date submitted <u>(817)6756495</u> <u>cgordon@firebirdenergy.com</u> Phone E-mail Address (OPTIONAL)			
RRC Use Only Data Validation Time Stamp: Oct 17, 2025 1:11 PM('As Approved' Version)							

Permit Status: Approved
<i>The RRC has not approved this application. Duplication or distribution of information is at the user's own risk.</i>

**RAILROAD COMMISSION OF TEXAS
OIL & GAS DIVISION**

APPLICATION FOR PERMIT TO DRILL, RECOMPLETE, OR RE-ENTER

*This facsimile W-1 was generated electronically from data submitted to the RRC.
A certification of the automated data is available in the RRC's Austin office.*

Permit # 911120
Approved Date: Oct 17, 2025

1. RRC Operator No. 101413	2. Operator's Name (exactly as shown on form P-5, Organization Report) FIREBIRD ENERGY II LLC	3. Lease Name TXL W 3542 H	4. Well No. 304H
Lateral Drainhole Location Information			
5. Field as shown on Form W-1 SPRABERRY (TREND AREA) (Field # 85279200, RRC District 7C)			
6. Section 42	7. Block 42 T5S	8. Survey T&P RR CO / TAYLOR, H F	9. Abstract 693
10. County of BHL UPTON			
11. Terminus Lease Line Perpendiculars 101 ft. from the SOUTH line. and 1284 ft. from the EAST line			
12. Terminus Survey Line Perpendiculars 101 ft. from the SOUTH line. and 1625 ft. from the WEST line			
13. Penetration Point Lease Line Perpendiculars 500 ft. from the SOUTH line. and 1579 ft. from the WEST line			

Permit Status:	Approved
<i>The RRC has not approved this application. Duplication or distribution of information is at the user's own risk.</i>	

**RAILROAD COMMISSION OF TEXAS
OIL & GAS DIVISION**

APPLICATION FOR PERMIT TO DRILL, RECOMPLETE, OR RE-ENTER

*This facsimile W-1 was generated electronically from data submitted to the RRC.
A certification of the automated data is available in the RRC's Austin office.*

W-1 Comments

Permit #	911120
Approved Date:	Oct 17, 2025

[Oct 13, 2025 10:41 AM]: Commission Staff expresses no opinion as to whether a 100% ownership interest in each of the leases alone or in combination with a "production sharing agreement" confers the right to drill across lease/unit lines or whether a pooling agreement is also required. However, until that issue is directly addressed and ruled upon by a Texas court of competent jurisdiction it appears that a 100% interest in each of the leases and a production sharing agreement constitute a sufficient colorable claim to the right to drill a horizontal well as proposed to authorize the removal of the regulatory bar and the issuance of a drilling permit by the Commission, assuming the proposed well is in compliance with all other relevant Commission requirements.

Issuance of the permit is not an endorsement or approval of the applicant's stated method of allocating production proceeds among component leases or units. All production must be reported to the Commission as production from the lease or pooled unit on which the wellhead is located and reported production volume must be determined by actual measurement of hydrocarbon volumes prior to leaving that tract and may not be based on allocation or estimation. Payment of royalties is a contractual matter between the lessor and lessee. Interpreting the leases and determining whether the proposed proceeds allocation comports with the relevant leases is not a matter within Commission jurisdiction but a matter for the parties to the lease and, if necessary, a Texas court of competent jurisdiction.

The foregoing statements are not, and should not be construed as, a final opinion or decision of the Railroad Commission.; [RRC STAFF Oct 15, 2025 10:30 AM]: Changed Y coordinates from 671069.95 to 671069.65; [RRC STAFF Oct 15, 2025 10:59 AM]: Changed well count from 12 to 10.; [RRC STAFF Oct 15, 2025 11:00 AM]: Changed Nearest Distance from the First/Last Take Point (Heel/Toe) to a Lease Line from 100 to 1.; [RRC STAFF Oct 15, 2025 11:00 AM]: Changed Nearest Perpendicular Distance from Any Take Point to a Lease Line from 1 to 986.; [RRC STAFF Oct 15, 2025 11:01 AM]: Changed BHL survey from A-1481 to A-693.; [RRC STAFF Oct 15, 2025 11:02 AM]: Changed Distance to Nearest Well from 646 to 644.; [RRC STAFF Oct 16, 2025 12:25 PM]: Changed well count from 10 to 11 per RRC records.; [RRC STAFF Oct 16, 2025 12:27 PM]: Changed lease line call for the LTP/BHL from 1625' FWL to 1284' FEL per plat.; [RRC STAFF Oct 16, 2025 12:30 PM]: There have been problems identified with this permit (see problem letter attachment). Notification sent.; [RRC STAFF Oct 17, 2025 11:30 AM]: Problems identified with this permit are resolved.; [RRC STAFF Oct 17, 2025 11:30 AM]: A revised P-16 has been attached showing the correct acreage assignments.; [RRC STAFF Oct 17, 2025 1:11 PM]: Exception Admin Approved. 37(h)(2)(B). Own Offset.